



TEXAS
SPEED & PERFORMANCE
101 Velocity Dr Ste 100
Georgetown TX 78628-3069

PH: 512-863-0900
customerservice@texas-speed.com

ROCKER ARM BOLT INSTALLATION

PART NUMBER: TSP-1052

COMPONENTS	QTY
BOLT	2

1. Make sure there is an adequate chamfer around the bolt hole to clear the radius under the head of the bolt.
2. Hand tighten the bolt.
3. Torque the bolts to **30** ft.lbs.

WWW.TEXAS-SPEED.COM